Title: Iceni House Whole House Risk Assessment

Date of Assessment: 2nd November 2023



Property Description: Iceni house is a two-storey residential facility, the whole facility has 16 bedrooms (sleeping 46 on the ground floor and 36 on the top floor) two dining rooms, on the ground floor there is a commercial kitchen, main hall and small multifunction room and on the top floor a lounge.

Key:

Severity Rating: 5 (Catastrophic) 4 (Major) 3 (Moderate) 2 (Minor) 1 (None)

Likelihood Rating: 5 (Almost certain) 4 (Likely) 3 (Possible) 2 (Unlikely) 1 (Insignificant)

Risk Rating:

0-5 = A (Acceptable Risk)

5-15 = RR (Residual Risk remains despite controls)

15-25 = U (Unacceptable Risk, action to be taken immediately)

Hazard: Main Kitchen	Severity	Likelihood	Risk
			rating
Control measures			
1. All electrical appliances tested regularly and maintained to a safe, high standard.			
2. Young people only to enter the kitchen under adult supervision.	2	3	RR
3. Warning signs displaced around the kitchen as appropriate.			(6)
4. Users shown how to work kitchen appliances on arrival.			

Hazard: Slips, Trips and Falls	Severity	Likelihood	Risk
			rating
Control measures			
Good Housekeeping practices to be followed.	2	3	RR
Sensor lighting provided in corridors.			(6)

Hazard: Hazardous Substances	Severit	/ Likelihood	Risk
			rating
Control measures	3	1	Α
All chemicals are locked away.			(3)
2. COSHH sheets are available in the cleaning cupboard in the event of an emergency			

Hazard: Electricity	Severity	Likelihood	Risk
•			rating

Reviewer: Susan Newton (Centre Manager)

Control measures			
1. Senior members of staff know location of mains and how to turn off in an emergency.	4	2	RR
2. Fixed wire and portable appliance testing take place on a regular basis.]		(8)
3. Guests are responsible for the safety of any electrical equipment that they bring onsite.			

Hazard: Fire	Severity	Likelihood	Risk
			rating
Control measures			
1. Fire Risk Assessment had taken place and measure have been implemented			
2. Fire Extinguishing equipment is provided and regularly inspected	4	2	RR
3. Fire call points and alarm is tested regularly.			(8)
4. Centre fire alarm is linked to the Fire Brigade			
5. Guests are advised to undertake a fire drill once all their party has arrived.			

This risk assessment should be read and used in conjunction with other centre specific site and activity risk assessments.