Eaton Vale Scout and Guide Activity Centre

Risk Assessment



Trapeze

Location

This activity takes place on a purpose-built structure at a height of 12 metres.

Equipment

A full body climbing harness is provided and fitted by the instructor. Helmets are provided and fitting is demonstrated. Other equipment may be used by the instructor as required.

Health & Hygiene

The activity takes place outside and is subject to the prevailing weather conditions. No special personal equipment is required other than normal clothing for the conditions. Footwear should be sensible for the activity and the conditions. The activity may take place in most weather conditions and the decision to start or stop a session is made with consideration given to the age, preparedness for the activity and experience of the group. The activity will not take place if there is the likelihood of lightning, heavy rain or high winds over 30mph.

COVID-19 Compliance amendments:

We continue to update and amend our COVID precautions and measures in relation to government guidelines and industry standards.

Hazard	Hazzard Effect	Action Recommended
Unauthorised access	Unsupervised persons	Restrict access by use of ladders covers, fencing and warning
to course.	on course falling from	signs.
	elements.	
Slips, trips, falls	Slight to severe injury.	Sensible outdoor shoes advised.
	(Bleeds, breaks,	Ensure before session that may require lighting that high ropes
	bruising)	outside lights are in a good working condition.
		All participants to be told to check where they are walking (to avoid ground anchors etc.)
Course structure	Course unsafe for use.	Course inaugural inspection by ERCA Type A to EN 15567 Part
vandalised or	Course urisale for use.	Course maugurar inspection by ERCA Type A to EN 19907 Part
damaged: severe		Annual inspection by ERCA inspector.
storms/winds.		Before session instructors to check that all aspects of course:
		elements and components are in working order.
Unqualified Staff.	Course not used	Staff should be suitably qualified and experienced before they
- 1	correctly.	are allowed to operate the course.
	PPE not fitted correctly.	
Extreme weather	Electrocution, unsafe	Adventure Constructions should not be used during electrical
conditions.	passage on elements.	storms heavy rain or wind conditions of more than 30 mph.
Participants falling or	Slight to severe injury.	All participants to be connected to the course PPE whilst off
slipping from height or	(Bleeds, breaks,	ground.
elements.	bruising.	Staff to fully brief participants on how to use equipment.
Objects falling from	Slight to severe injury.	All participants to remove objects from pockets, loose jewellery,
above.	(Bleeds, breaks, bruising.	all PPE to be CE approved and fitted correctly.
Inappropriate clothing	Participants unable to	Instructors to ensure that Participant is wearing appropriate
or footwear.	negotiate course friction	clothing and footwear, open toed shoes are not allowed.
or rootwear.	or other injuries caused	olouting and tootwear, opon took shoes are not allowed.
	by PPE or elements of	
	course.	
Incapacity of	Participants unable to	Relevant medical conditions are made available to instructors.
Participants.	complete course,	Instructors to assess Participants before allowing access to
	unnecessary trauma,	course.
	rescues required.	

Last updated 3 November 2023 Next review date 3 November 2024 **Sam Fenton** Deputy Manager

Eaton Vale Scout and Guide Activity Centre





Snagging of Jewellery or other personal	Entrapment injuries.	Instructors to advise Participants to remove all loose jewellery.
property.		
Snagging of hair.	Entrapment injuries.	Instructors to ensure participants tie back long hair.
Chewing gum or other food whilst on the course.	Choking.	Instructors to advise Participants not to chew gum or eat whilst on the course.
Trapped participants.	Instructors unable to rescue Participant.	Staff trained in Rescue Training.
Badly fitted PPE.	PPE is not suitable for participant.	Small or large people will not be able to use the course those under 1.2M tall or weighing over 120Kgs should not be allowed to access the course.
New or Wet lines or PPE.	Equipment slippery or stiff.	Instructors to handle new or wet equipment cautiously.
Participant collision with platform	Slight to severe injury. (Bleeds, breaks, bruising)	Instructor to take in slack when participant jumps Instructor to time lowering to minimise chance of participant colliding with platform Participants reminded to try and stick out limb to stop collision with plat form Platform lined with rubber to minimise injury on collision
Bumping in to holds on the wall on decent	Slight to severe injury. (Bleeds, breaks, bruising).	Slow controlled decent. No sudden drops or quick descent.